OWNER'S MANUAL

ARC WELDING CART WITH CYLINDER RACK (1661551)

A WARNI

ELECTRIC SHOCK can kill

- Do not touch live electrical parts.
- Turn off welding power source and input disconnect device.
- Disconnect input plug or power conductors from deenergized supply BEFORE moving welding power source.



FALLING EQUIPMENT can cause injury and damage, OVERSIZED CYLINDER can cause tipping.

- Move unit with proper handcart.
- If using a fork lift vehicle, secure unit on a skid.
- Never lift unit with cylinder attached.
- Maximum cylinder weight is 75lbs (34kgs).

Tools Needed



CYLINDERS can explode if damaged.

- Keep cylinders away from welding and other electrical circuits.
- Never touch cylinder with welding electrode
- Always secure cylinder to running gear, wall, or other stationary support.








Item No. Description (Qty)

- 1 Bottom Tray (1)
- 2 Support Frame(2)
- 3 Caster (2)
- 4 Bottle Bracket (1)
- 5 Top Tray (1)
- 6 Axle (1)
- 7 Wheel, 6 in (2)
- 8 Chain, 24 in (1)
- 9 Tubing Plug (4)
- 10 Warning Label (1)
- Hardware Kit (consisting of)
- 11 Nut, M-8(2)
- 12 Lockwasher, M-8(2)
- 13 Flat Washer, M-8(2)
- 14 Cotter Pin (2)
- 15 Spacer (2)
- 16 Flat Washer, M-12(4)
- 17 Screw, M-5x12(10)
- 18 Flat Washer, M-5 (10)
- 19 Nut, M-5(2)

Be sure to provide Model when ordering replacement parts.



Assembly order:

- 1 Assemble bottom tray, casters, axle and wheels to frame supports.
- 2 Install bottle bracket by hooking it through bottom tray slot.
- 3 Install top tray to frame supports and bottle bracket.