



BX- 12 Instructions



1. Remove hing tubes from gate and install in extension as shown. Tighten set screw at top and use 7/8" bolt at bottom.



2. Connect extension to gate frame as shown using 5" connecting bracket at top with 1" phillips head bolts and lock nuts. Connect bottom using short bracket and 1/4" x 1" hex bolt and lock nuts as shown.

Attach to surface according to gate mounting instructions.

