



GREAT STUFF PRO™ Window & Door Polyurethane Foam Sealant Kit Instructions

INSTRUCTIONS :

Read entire can label carefully.

Failure to follow all directions can result in injury or death.

Recommended usage temperature: 60-90°F (15-32°C) Optimal 75°F (23°C)

Handle responsibly. Plan. Prepare. Practice.

Use protection to avoid all contact with skin and eyes, such as gloves and safety glasses.

SHAKE vigorously - minimum 60 seconds.

Invert can and screw onto adapter of the foam applicator gun.

Adjust flow control screw on back of foam applicator gun to an open position.

Immediately press trigger to fill applicator gun with foam while dispensing into an appropriate waste receptacle.

Keep can inverted during use.

Use flow control screw to adjust bead size.

Tighten the flow control screw until fully closed for storage. Use can within 30 days of initial use.

Store upright with foam applicator gun attached.

To reuse, shake well. Adjust flow control to an open position.

Fill gaps <50%. Mist water to speed cure. Not to be used for filling closed cavities or voids.

If product does not flow easily, do not force product from can.

CHANGING CANS :

Always leave a can of foam attached to gun, with the flow control screw closed.

When ready to change cans, shake the new can of foam - minimum 60 seconds. Unscrew empty can.

Use GREAT STUFF™ Foam Cleaner to clean uncured foam from gun assembly.

Immediately screw on new can of foam.

Immediately press the trigger to fill gun with foam.

NEVER leave a gun without a can of foam attached unless it has been thoroughly cleaned with GREAT STUFF™ Foam Cleaner.

CLEAN UP :

For uncured foam, use GREAT STUFF™ Foam Cleaner or acetone.

Skin and cured foam – all adhesive must be mechanically removed or allowed to wear off in time.

GREAT STUFF PRO™ Window & Door Polyurethane Foam Sealant not for use in aviation, or food/beverage contact, or as structural support in marine applications.

**For questions and concerns, contact:
customerservice@mpexport.com**