



6023-2979 Folding Drying Rack ©2010 Whitmor



A 1 ea
Left side frame



B 1 ea
Right side frame




C 11 ea
Hanging bar

Assembly Time:
Less than 15 minutes.


This product's intended use is for drying laundry.

Tools Needed: No tools required


STEP 1. Lay the left side frame (A) on the floor or hard surface. Insert all the hanging bars (C) onto left side frame by sliding each one into the connectors on the side frame.



STEP 2. With all hanging bars assembled onto the left side frame, place the right side frame (B) onto top aligning and sliding each hanging bar into the connectors on the right side frame.



STEP 3. Set drying rack upright and lock the top by sliding the slots together. Assembly is now complete. Your drying rack can be folded down for easy storage after use. Enjoy your new Whitmor folding drying rack.



Part	Reference
A	F7114
B	F7115
C	F7116

MADE IN CHINA



8680 Swinnea Road • Suite 103 • Southaven, MS • 38671

NEED HELP? For help with assembly, or if you are missing a part, please call Whitmor's Customer Service Department, 1-888-944-8667 between 8 a.m. and 4:30 p.m. (Central Standard Time) Monday through Friday. Or email: customer_service@whitmor.com