


	Part	Reference
	Α	F11389
	В	F11390
	С	F11391
	D	F11392
	Е	F11393
	F	F11394
Γ	G	F11395




No tools required.




B 4 ea Long Pole


C 2 ea Hanging Rod




D 10 ea **End Connector**



E 3 ea Middle Connector



F 5 ea **Short Shelf**




G 2 ea Long Shelf



STEP 1: Start by assembling the top, bottom and middle sections.


- □ Bottom Section: Insert the long shelf (G) and the short shelf (F) into two end connectors (D) and one middle connector (E) as shown below.
- ☐ **Top Section:** Repeat the step above while inserting the hanging rod **(C)** into end connector **(D)** and middle connector **(E)** as shown below.
- ☐ Middle Section: Insert the hanging rod (C) and the short shelf (F) into the two end connectors (D) and one middle connector (E) as shown below.

Note: All metal parts must be inserted firmly and completely into the plastic parts.



©2023 Whitmor, Inc.






©2023 Whitmor, Inc.



STEP 3:

Start from the assembled bottom section and build up.

☐ Insert short and long poles (A) and (B) into the connectors as the diagram shows.



8680 Swinnea Road • Suite 103 • Southaven, MS • 38671

NEED HELP? For help with assembly, or if you are missing a part, please call Whitmor's Consumer Care Team, 1-888-944-8667 between 8 a.m. and 4:30 p.m. (Central Standard Time) Monday through Friday, or email: help@whitmor.com. Visit us online at www.whitmor.com

Rev#5 | 07.21.23 Printed in Vietnam