MONITOR SOIL TEMPERATURE FOR HEALTHY SEEDING, POTTING, PLANTING, AND GARDENING

SHATTER-RESISTANT PLASTIC LENS

7-IN (17.8 CM) STAINLESS STEEL PROBE

INCLUDES PROTECTIVE SHEATH WITH POCKET CLIP

Directions:

For accurate temperature measurement, insert probe at least 2 inches into the soil. Leave for one minute or more.

Recalibration:

To check your thermometer for accuracy, immerse probe 2 inches into a cup of ice water. Without removing probe, grip the calibration nut (see Figure A) with a suitable tool and rotate the thermometer until it reads 32°F. Allow a minimum of 30 seconds before readjusting.

