



INSTRUCTIONS FOR USE INSTRUCCIONES DE USO


For installation of the following items: FV15H, FV30

PIPE WRAP INSULATION TAPE Self-Adhesive Foil and Foam

Instructions:

1. For best results, ensure the pipe to be insulated is dry and free of dust, grime or grease.
2. Coil the tape loosely along the length of the pipe.
3. Press it in place with the edges butted together so that none of the pipe is exposed.

***"R" means resistance to heat flow. The higher the R value, the greater the insulating power.*





CINTA DE AISLAMIENTO PARA TUBERÍAS Espuma autoadhesiva con revestimiento de aluminio


Instrucciones:

1. Para mejor resultado, asegúrese de que la tubería a aislar esté seca y libre de polvo, sucio o grasa.
2. Enrolle holgadamente la cinta a lo largo de la tubería.
3. Presiónela en su lugar, juntando las orillas a tope, de manera que no quede expuesta ninguna parte de la tubería.

***"R" significa resistencia al flujo de calor. Cuanto más alto es el valor de R, mayor es la energía aislante.*



Can be formed to fit any bend or valve.
Puede ser moldeado para adaptarse a cualquier codo o válvula



Weather Resistant / Resistente a las inclemencias del tiempo

TOOLS NEEDED:

HERRAMIENTAS NECESARIAS:



Follow Us @FrostKing
or www.frostking.com



Thermwell Products Co., Inc.
Mahwah NJ 07430 | Sparks NV 89431

Need help or information
about any Frost King product?
Call **1-877-FROST 20**
3 7 6 7 8

For videos, instructions, hints and tips
visit www.frostking.com/instructions