Guide Manual

1/ Check the model No. of your welder, this replacement MIG if fully compatible with Power MIG 200, 215, 216, 255 and the Wire Matic 255.

2/ Insert the MIG gun to the connection hole and conduct the welding to check if can work properly.